

ENGINE PAINT SEALING LOCATIONS BRIGGS and STRATTON WORLD FORMULA

- 1. Carburetor nut to rubber insulator
- 2. Clamp on black insulator to manifold
- 3. Intake manifold to block
- 4. Head bolt
- 5. Side cover to block
- 6. Shroud bolt
- 7. Flywheel nut
- 8. Seal valve cover
- 9. Float bowl screw
- 10. Exhaust flange nut.
- 11. Paint Qualifying number on frame
- 12. Paint Qualifying number on valve cover